Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

GB899 MANHOLE #56986 NY Spills S108294641
ENE 1022 AVE Y N/A

1.200 mi.

> 1

6336 ft. Site 2 of 2 in cluster GB

BROOKLYN, NY

 Relative:
 SPILLS:

 Higher
 Name:
 MANHOLE #56986

 Actual:
 Address:
 1022 AVE Y

 11 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0607545 / 2006-12-21

 Facility ID:
 0607545

 Facility Type:
 ER

 DER Facility ID:
 321072

 Site ID:
 371296

 DEC Region:
 2

Spill Cause: Equipment Failure

 Spill Class:
 C4

 SWIS:
 2401

 Spill Date:
 2006-10-02

 Investigator:
 JHOCONNE

 Referred To:
 Not reported

 Reported to Dept:
 2006-10-03

 CID:
 78

Water Affected:
Spill Source:
Commercial/Industrial
Spill Notifier:
Cleanup Ceased:
Cleanup Meets Std:
Last Inspection:
Recommended Penalty:
UST Trust:
Not reported
False
Not reported
False
False

UST Trust: Fa
Remediation Phase: 0

Date Entered In Computer: 2006-10-03

Spill Record Last Update: 2006-12-21

Spiller Name: Not reported

Spiller Company: CON ED

Spiller Address: Not reported

Spiller Company: 999

Contact Name: ERTS

DEC Memo: "12/21/06 - See e-docs for Con Ed report detailing cleanup and

closure. Con Ed no. 202732 - see eDocs."

Remarks: "1 pint unknown oil in 300 gallans of water in earthen sump con ed

ref #202732 "

All Materials:

 Site ID:
 371296

 Operable Unit ID:
 1129065

 Operable Unit:
 01

 Material ID:
 2118725

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00

Oxygenate: Not reported